

NOTE TO FILE  
From: K. Rodriguez  
6/29/2010

Site Name: Flying B 29  
UST ID: 10589

On June 24, 2010, Arthur Buchan, a NACE certified Ecology inspector, provided cathodic protection training at the Flying B 29 facility for three Ecology inspectors. I attended the training.

The facility has both galvanic and impressed current systems. Based on the results, I contacted Gary Bains and provided a courtesy reminder that his CP testing was overdue (last 4/2007) and that preliminary testing results show that the CP systems are failing the continuity and/or system surveys. The results of the testing are attached.

I told him he should plan to have the system tested within 30 days. He said it would happen sooner than that. He also said the STI-P3 tanks are the newest and the 4K tank (material unknown during the site visit but appeared not to be steel) was likely going to be removed. He is considering upgrading the dispensers and putting in dispenser sumps.